



Security Cove Cr.
Lake System



104-10-10:70

Name Security Cove - Head Catalog No. 104-10-27
 Latitude 54° 45' 04" WR No. _____
 Longitude 132° 49' 08" 15" K No. _____
 Geodetic Map No. Dixon Ent - D-3 Work Area Ketchikan
 Location West Coast Dall Island Watershed Length 1.5 miles
 Drainage Area of Watershed _____
 Water Supply Type Drains a lake, precipitation.

Trails & Survey Routes Easiest walking is in the stream or stream banks, not too brushy.
 Aerial Survey Notes Could survey the I.T.Z. but too brushy above this for surveying.
 Anchorage As you enter Security Bay anchor in the first small bight on the left.
 Tide Stage When Surveyed Low tide.

FISHERY RESOURCES

Commercial Fisheries Unknown, probably pink, chum and coho.
 Escapement 500 at the mouth on 8-27-70.
Available spawning area - 293 M²
 Species Composition Probably pink and chum.
 Timing Late
 Schooling areas Off the mouth.
 Shellfish Potential Somewhat rocky but could be some clams. No crab pots were set.
 Sport Fisheries Unknown but not much potential.
 Land Use at Present None
 History of Land Use None
 Rehabilitation Potential Too small, not enough potential.
 Soils Stable to the point walked.

GAME RESOURCES

Bear -----	Fish carcasses or bones (old or fresh) on banks, estimate	0
	Number of droppings	0
Geese -----	Number seen on tide flats	0
	Number seen up creek	0
	Number of broods seen	0
Mallards ---	Number seen on tide flats	0
	Number seen up creek	0
	Number of broods seen	0
Mergansers -	Number of broods seen	0
Bald Eagles-	Number seen along creek	0
	Number of nests seen and location	0
Seals -----	Number seen at mouth of stream	0
Tide flats -	Estimate length along beach	
	Estimate depth out from beach	
	Red grass present on what percent of flats	5%